

Community Advisory Group
Mills Gap Groundwater Contamination Site
EPA NCSFN0406988 a.k.a. CTS of Asheville, Inc. Site
EPA ID NCD003149556
82 Southside Village Drive
Asheville, NC 28803

FEDEX OVERNIGHT

May 18, 2009

The Honorable Beverly Eaves Perdue, Governor
Office of the Governor
113 West Jones Street
Raleigh, NC 27601

Re: CTS of Asheville /Mills Gap Road Associates Toxic Disaster Site, Docket # 97-SF-132

Dear Governor Perdue:

The mountain of information and petitions you are receiving is necessary in order to inform you of the critical situation that we find ourselves in today, regarding the CTS/ Mills Gap Road Association Superfund site in South Asheville / Arden, NC.

The informational material clearly shows a pattern of gross negligence by NC DENR to protect the lives, health and property of those residing in the toxic plume drainage areas of the site. Neighborhood graveyards and hundreds of tragic health histories of your fellow citizens in the toxic areas all testify to the truth of that statement.

Another truth you can be assured of is that many thousands of area residents, all Buncombe County Commissioners, and all on Asheville City Council clearly understand that if NC DENR enters into any voluntary cleanup agreement with CTS, their toxic legacy will continue to expand at our expense.

We cannot urge you strongly enough, to decline a voluntary cleanup agreement with CTS. In its place, we petition you to order an immediate mandatory cleanup of the site as provided by law.

In doing so, you will restore the confidence we need to have in our government. Much more importantly however, you will have placed the health, safety and welfare of your fellow citizens above all other interests.

Sincerely,

A handwritten signature in black ink, appearing to read 'Glen E. Horecky', with a long horizontal stroke extending to the right.

Glen E. Horecky, RFC, CSA
Community Advisory Group (CTS of Asheville Site)
President

Enc.